

## **Canopy Arm Quality Issues Investigation Status** June 6, 2019



## **Canopy Quality Issues**

- HART was notified of quality issues on two of the station groups
- On the FHSG group, cracks in the steel were observed in 4 canopy arms not yet shipped
- Initial investigation indicates that the canopy arms may have developed cracks during the galvanizing process
- The 10 canopy arms that have been delivered to site are not being installed at this time
- HART has put both the contractor and designer on notice, and both are cooperating in developing an analysis and a resolution to the issue



## **Canopy Quality Issues**

- The second of two of the station groups is WOSG
- On the WOSG group, cracks in the steel were observed in 1 canopy arm that was shipped to the site
- 16 canopy arms have been delivered to site and all except the one with the crack have been installed
- HART has put both the contractor and designer on notice, and both are investigating a potential fix



### **Defects**

West Oahu Station Group – Ho'opili Station



Lower frame segment crack – 1 Frame Nan, Inc. & TMP (fabricator)

Farrington Highway Station Group


– West Loch Station (WLO)



Lower frame segment cracks – 4 Frames HDCC, Inc. & SSW (fabricator)



## **Background**



Side Platform Frame

Center Platform Frame



## **Quality Issues**

West Oahu Station Group (Nan, Inc.)	Farrington Highway Station Group (HDCC, Inc.)	Kamehameha Highway Station Group (Nan, Inc.)
Contractor Notification to HART: Last week April	Contractor Notification to HART: Last week April	Notified: None
1 lower segment (Ho`opili - side platform) delivered cracked (Gr 100)	4 cracked lower segments @ factory in KS (WLO)	Proceeding with Center Platform fabrication (Gr 50)
All other frames erected	10 lower segments delivered to MSF (WTC)	Side Platform (Gr 100 Elements) – On Hold
Collecting documentation	Cracks occurred after welding, possibly during galvanizing	HART notified contractor & designer
HART notified contractor & designer	HART notified contractor & designer	
	Parties are cooperating, developing an analysis and resolution	




## **Approach**

#### HART's Goals & Objectives for Roof Canopy Structures

- A. Establish that Design is safe, and that Construction delivers on Design requirements
- B. Based on metallurgical science and engineering, get failure analysis underway and establish causal contributing factors
- C. Determine structural adequacy of fabrications performed and decide on their disposition
- D. Determine the need for any modifications to current design and specifications
- E. Determine the need for any modifications to current contractor/fabricator means & methods
- F. Develop "Plan B" to fast-track alternate design and fabrication activities to avoid potential program delays associated with reported risks of high strength Gr 100 steels



## FHSG Investigation – Task Force Team






## **Preliminary Analysis**

- WOSG collecting documentation; field weld repair was unacceptable
- FHSG canopy frame lower segment analysis begun 80%-90% of crack filled with zinc (galvanizing material)
- Preliminary hypothesis based upon Wiss, Janney, Elstner (WJE) assessment: Cracks are result of either liquid metal embrittlement (LME), hydrogen embrittlement (HE) or strain age embrittlement
- High residual stresses due to fabrication methods (e.g. welding and plasma cutting) and thermal shock due to hot dip galvanization (HDG) Lower segment is Grade 100 steel
- KHSG Gr 100 fabrication on hold



## FHSG Action Plan/Schedule





## Questions



# Mahalo!

